

Maryland Historical Trust

State Historic Sites Inventory Form

Magi No.

DOE ☐ yes ☐ no

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

18912 Sandy Hook Road JH 12/1/05street & number north side of Sandy Hook Road, .35 mile east of Clark Road not for publicationcity, town Sandy Hook ☐ vicinity of ☐ congressional district sixthstate Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> religious
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> scientific
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title

date ☐ federal ☐ state ☐ county ☐ local

depository for survey records

city, town state

7. Description

Survey No. WA-III-088

Condition

☐ excellent
☒ good
☐ fair

☐ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. The main section is six-bays by two-bays with a full-length, one-story porch. The exterior has a vertical board siding. The structure has a gable roof covered in sheet metal. The structure appears to date from the late 19th century.

The property is located on the north side of Sandy Hook Road, approximately .035 mile east of Clark Road, in Sandy Hook. The structure sets right up on the road. The main facade faces south.

The two-story structure is constructed of frame covered in a vertical board siding. The structure is on a fieldstone foundation with a full-length, one-story front porch on a concrete block foundation. The front porch has a hipped roof covered in sheet metal and is supported on chamfered posts. The first story of the main section has six bays with entrances in the second and fifth bays. One-over-one sash windows are in the other bays of the first story. On the second story, windows are in the bays above the windows of the first story (with the bays above the doors being unfenestrated). The gable ends have windows on the first and second story and small windows in each gable. Some of the sash on the gable ends have six-over-six pane which is probably what was originally on the structure. The house has a gable roof covered in sheet metal. Interior-end brick chimneys rise from each gable end.

8. Significance

Survey No. WA-III-088

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☒ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G


Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook
Survey District.

WA-III-032, Sandy Hook Survey District

(All prefixes "WA-III-")




WA-III-088

Frame House

18912 Sandy Hook Road (MD 180), Sandy Hook

Harpers Ferry Quadrangle



1993-94 Aerial Photo



FREDERICK & INGTON


HARPERS FERRY, VA-MD-W VA
QUADRANGLE

USGS 7.5 minute map

1:24 000

1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST





1. WA-III-088
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1